ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: M09435 Date Received: 08/30/12 Date Extracted: 08/31/12 Date Analyzed: 08/31/12 Matrix: Water Units: ug/L (ppb)

Client: Project: Lab ID: Data File: Alaskan Copper Works

Metro Self Monitor M09435, F&BI 208449

208449-01 x10 208449-01 x10.048

Instrument: ICPMS1 Operator: AP

Lower

Upper

Internal Standard: Germanium

% Recovery:

Limit: 60

Limit: 125

Concentration

Analyte: Chromium ug/L (ppb) 140 106

Copper Zinc

Nickel

178 10.5

ENVIRONMENTAL CHEMISTS

Client:

Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank
Date Received: Not Applicable
Date Extracted: 08/31/12
Date Analyzed: 08/31/12
Matrix: Water
Units: ug/L (ppb)

Project: Metro Self Monitor M09435, F&BI 208449
Lab ID: I2-565 mb
Data File: I2-565 mb.030
Instrument: ICPMS1
Operator: AP

Internal Standard: Germanium

% Recovery:

Lower Limit: 60 Upper Limit: 125

Alaskan Copper Works

Concentration
Analyte: ug/L (ppb)

Chromium <1

 Nickel
 <1</td>

 Copper
 <1</td>

 Zinc
 <1</td>

ENVIRONMENTAL CHEMISTS

Date of Report: 09/11/12 Date Received: 08/30/12

Project: Metro Self Monitor M09435, F&BI 208449

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 208457-01 (Matrix Spike)

Analyte	Reporting Units	Spike Level	Sample Result	Percent Recovery MS	Percent Recovery MSD	Acceptance Criteria	RPD (Limit 20)
Chromium	ug/L (ppb)	20	1.14	83	89	71-130	7
Nickel	ug/L (ppb)	20	3.22	82	89	71-120	8
Copper	ug/L (ppb)	20	<1	79	85	52-134	7
Zinc	ug/L (ppb)	50	4.39	83	86	51-142	4

Laboratory Code: Laboratory Control Sample

	Percent									
	Reporting	Spike	Recovery	Acceptance						
Analyte	Units	Level	LCS	Criteria						
Chromium	ug/L (ppb)	20	96	80-119						
Nickel	ug/L (ppb)	20	101	83-119						
Copper	ug/L (ppb)	20	101	81-120						
Zinc	ug/L (ppb)	50	100	82-120						

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb Analyte present in the blank and the sample.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht Analysis performed outside the method or client-specified holding time requirement.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- ${\bf J}$ The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve Estimated concentration calculated for an analyte response above the valid instrument calibration range. A dilution is required to obtain an accurate quantification of the analyte.
- vo The value reported fell outside the control limits established for this analyte.
- \mathbf{x} The sample chromatographic pattern does not resemble the fuel standard used for quantitation.

Send Report To GERNO THOOPEN Company Acasta Cooper Works Address 628 S. Handed ST			PRÔJECT NAME/NO. PO# METER SELE MO1TOL M09435					-	TURNAROUND TIME Standard (2 Weeks) USH Rush charges authorized by:							
City, State, ZIP <u>56</u> Phone (26) 571-6	971E 0	A 782-9	813 <u>4</u> 1309	REMARKS	Y					WAYN	ana n		O R	ispose eturn s fill call	IPLE DIS after 30 d samples with inst	lays
Sample ID	Lah ID	Date	Time	Sample Type	# of containers	TPH-Diesel	TPH-Gasoline	BTEX by 8021B	\neg	SVOCe by 8270 N	75	EAG	EST EL			Notes
M09435	01	3/3/n	11:15	H20	1			\exists	+		X	-				
		,										1		-		
													\pm			
									1							
		2.	n.						1		Ŧ	1			mV.	
012 16th Avenue West RAD			GNATURE		PRINT NAME GREAT THOUSAN					ACW STANY			1	DATE	TIME 12:20 _m	
eattle, WA 98119-2029 h. (206) 285-8282 ex (206) 283-5044	Received by:			Michel Crobbl					Fahre				1			
RMS\COC\COC.DOC		1		<u> </u>	*	-			12	1		Sai	pples	recei	ved at	<u>13</u> ℃

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 e-mail: fbi@isomedia.com

September 11, 2012

Gerald Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on August 30, 2012 from the Metro Self Monitor M09435, F&BI 208449 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures